



Job #4

VOLKSWAGEN · Caddy · BLUE

POC

POD



224.1 mi

Route distance

Empty

Required delivery fuel

Collection vs delivery

	POC — COLLECTION	POD — DELIVERY
Staff	Driver	Driver
Submitted	17/08/2026, 10:28:56	18/08/2026, 09:21:41
Mileage	28,769 mi (46,299 km)	29,045 mi (46,743 km)
Fuel	1/8	1/8
Charge	—	—
Location		

Comparison against collection

2

New since collection

0

Worsened

0

Pre-existing, unchanged

0

Resolved since collection

Collection (POC) (7)



Scuff / scrape

O/S rear door

Minor

Light scuff mark near the bottom edge of the rear door above the sill.



Bumper trim/moulding damage

Rear bumper

Moderate

Dark trim/rubber strip on rear bumper appears scuffed and misaligned near the corner.



Scratch

N/S front door

Minor

Faint horizontal scuff mark on lower front door panel near the door handle area.



Scratch

N/S rear door

Moderate

Horizontal scratch/scuff line running along the lower body crease of the rear door, extending toward the front door.





Dent with paint damage

O/S rear door


Moderate



Alloy/wheel scuff (kerbing)

O/S front wheel

Minor



Alloy/wheel scuff (kerbing)

N/S front wheel

Minor

New since collection (2)**Scuff / scrape**

O/S sill

Minor

Dark smudge/scuff mark along the lower sill area between wheels.

**Warning light on**

Dashboard

Moderate

Fuel warning light (low fuel, range 10 mi)

Worsened (0)

None.

Pre-existing, unchanged (0)

None.

Resolved since collection (0)

None.

Collection (POC) photos



Dashboard



Keys

Delivery (POD) photos




Dashboard




Keys

Sign-off


COLLECTION



Staff (Driver)



DELIVERY



Staff (Driver)

